HAER No. CO-15

HISTORIC AMERICAN ENGINEERING RECORD INDEX TO PHOTOGRAPHS

NAME:

Terminal Dam (Tacoma Project)

LOCATION:

Tacoma Vicinity

La Plata County, Colorado

Martin G. Robbins & D. Paul Hathaway, Photographers

1980

CO-15-1 through CO-15-11: original photographs in files of Colorado-Ute

Electric Association, Inc., Montrose, Colorado.	
CO-15-1	Photocopy of photograph1903 (2 1/4 X 2 1/4" negative) VIEW DURING CONSTRUCTION
CO-15-2	Photocopy of photograph1903 (2 1/4 X 2 1/4" negative) VIEW DURING CONSTRUCTION
CO-15-3	Photocopy of photographWinter 1903-1904 (2 1/4 X 2 1/4" negative) VIEW DURING CONSTRUCTION
CO_15-4	Photocopy of photographWinter 1904 (2 1/4 X 2 1/4" negative) VIEW DURING CONSTRUCTION
CO-15-5	Photocopy of photographSpring 1905 (2 1/4 X 2 1/4" negative) VIEW OF UPSTREAM FACE
CO-15-6	Photocopy of photographSummer 1905 (2 1/4 X 2 1/4" negative) VIEW OF DOWNSTREAM FACE
CO-15-7	Photocopy of photograph1905 (2 1/4 X 2 1/4" negative) GENERAL VIEW
CO-15-8	Photocopy of photographApril 1907 (2 1/4 X 2 /14" negative) VIEW DURING CONSTRUCTION OF NEW OUTLET WORKS
CO-15 - 9	Photocopy of photographMay 1907 (2 1/4 X 2 1/4" negative) VIEW SHOWING NEW OUTLET TUNNEL
CO-15-10	Photocopy of photograph (2 1/4 X 2 1/4" negative) GENERAL VIEW

CO-15-11	Photocopy of photograph1909 (2 1/4 X 2 1/4" negative) VIEW OF TERMINAL DAM AND POWER FLUME #1
CD-15-12	FRONTAL VIEW; UPSTREAM FACE OF DAM1980
CO-15-13	FRONTAL VIEW; UPSTREAM FACE DF DAM198D
CD-15-14	SIDE VIEW; WEST END DF UPSTREAM FACE DF DAM1980
CD-15-15	SIDE VIEW; DETAIL DF UPSTREAM FACE DF DAM1980
CD-15-16	SIDE VIEW; DETAIL DF UPSTREAM FACE DF DAM1980
CO-15-17	FRONTAL VIEW; UPSTREAM FACE OF DAM FROM EAST BANK198D
CD-15-18	SIDE VIEW; EAST END DF UPSTREAM FACE DF DAM198D
CD-15-19	SIDE VIEW; CREST OF DAM1980
CD-15-20	SIDE VIEW; DOWNSTREAM FACE DF DAM TDWARDS EAST END1980
CD-15-21	SIDE VIEW; DOWNSTREAM FACE OF DAM WITH SEEPAGE PDND IN FDREGRDUND
CO-15-22	GENERAL VIEW; ELECTRA LAKE FRDM CREST OF DAM AT EAST END198D